



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

January 3, 2006

Supervisor *[Signature]*

Mine Name: Morton Salt - Grantsville
Operator Name: Morton International, Inc.

Permit number: M0450037
Inspection Date: October 26, 2006
Time: 7:30 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: Jim Huizingh

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

1. This site is active. I met with Mr. Huizingh and discussed the Division's role in regulating this type of operation. He was currently reviewing the reclamation surety renewal notice (billing statement) from his surety company. Not knowing what the surety was for - he was about to have it cancelled. After explaining what it was, he immediately forwarded it for payment.

We toured the surface facilities during this inspection. The site was free of trash. Drainages appeared to be functioning properly. One building had sustained some damage from recent high winds - I was informed that materials were ordered to make the repairs.

With the overnight storm and precipitation, it was decided to stay off the dikes during this inspection. The ponds will be inspected during the next inspection.

Photos were taken to document site conditions.

Conclusions and Recommendations:

1. This operation appeared to be in compliance with the current permit and regulations. Continue to inspect this site on a regular basis. Next inspection should be scheduled during a 'dry' season so that the ponds can be inspected.

Inspector's Signature *[Signature]*

Date: January 3, 2007

LK:pb

O:\M045-Tooele\M0450037-mortonSalt-grantsville\inspections\insp-10262006.doc